

Work Order ID 76730***76730***

Page 1

Thursday, November 24, 2011 11:42:46 AM

Item ID: D2661-1

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Saddle, LH Fwd Aft Out 206

Start Date: 11/21/2011 Start Qty: 2.00 ***2***

Cust Item ID:

Required Date: 11/22/2011 Req'd Qty: 2.00 ***2***

Customer: CU-DAR001

Reference: RMA RA111290 -RETURN

Approvals: Process Plan: *MLF*

Date: 11-11-24 Tooling:

Date:

Run Start ***NR1***

QC:

Date: SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2661	Rev E								

100

0.00

100

QC

Memo

0.00

Quality Control

RA INSPECT 111290 D2661-1 X 2 B64559

SADDLES WERE MADE UNDER OLD PROGRAM

PLACE UNDER QUARANTINE ON MEZZ

110

Identify as per dwg & Stock Location: *NDZ* 0.00***110***

Packaging

Memo

0.00

Packaging

ID AND STOCK UNDER NEW BATCH NUMBER ON MEZZANINE
QUARANTINE

Work Order ID 76730***76730***

Page 2

Thursday, November 24, 2011 11:42:46 AM

Item ID: D2661-1

Accept

N900040100

Setup Start

NS1

Revision ID:

Stop

NS2

Item Name: Saddle, LH Fwd Aft Out 206

Start Date: 11/21/2011 Start Qty: 2.00

2

Cust Item ID:

Required Date: 11/22/2011 Req'd Qty: 2.00

2

Customer: CU-DAR001

Reference: RMA RA111290

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

120

QC21- Final Inspection - Work Order Release

0.00

120

QC

Memo

0.00

QUARANTINED ON MEZZ.
NO QC21 ON SYSTEM.

11/12/13

J

Quality Control

MF
11-12-13